

Cam locks for the MAC-50 crane were found unserviceable during repair. The cam locks were not available through the supply system. MDMC designed and printed the cam locks out of MS-1 Maraging Steel in order to return the MAC-50 cranes to service.

